

# Search Superfund Site Information

## PHILLIPS THOM LANDFILL

### Site Information

[Site Info](#) | [Aliases](#) | [Operable Units](#) | [Contacts](#)  
[Actions](#) | [Contaminants](#) | [Site-Specific Documents](#)

**Site Name:** PHILLIPS THOM LANDFILL

**Street:** CORNER US ROUTE 30 & ACUTT ROAD

**City / State / ZIP:** MONTGOMERY, IL 60538

**NPL Status:** Not on the NPL

**Non-NPL Status:** NFRAP-Site does not qualify for the NPL based on existing information

**ERS Exclusion:** An Eligible Response Site (ERS) Exclusion decision has been made at this site.

**EPA ID:** ILD980902134

**EPA Region:** 05

**County:** KANE

**Federal Facility Flag:** Not a Federal Facility

EPA Region 5 Records Ctr.



362152

# Search Superfund Site Information

## PHILLIPS THOM LANDFILL

### Aliases

[Site Info](#) | [Aliases](#) | [Operable Units](#) | [Contacts](#)  
[Actions](#) | [Contaminants](#) | [Site-Specific Documents](#)

#### Alias Name / Street / City / State / ZIP

PHILLIPS THOM LDFL  
CORNER US RTE 30 & ACUTT RD  
MONTGOMERY, IL 60538



[http://oaspub.epa.gov/enviro/multisys2.get\\_list?facility\\_uin=110009326746](http://oaspub.epa.gov/enviro/multisys2.get_list?facility_uin=110009326746)  
Last updated on Thursday, August 12, 2010

## Envirofacts Data Warehouse

You are here: [EPA Home](#) [Envirofacts](#) [Multisystem](#) [Report](#)



### MultiSystem Report

Report  
an  
Error

#### PHILLIPS THOM LANDFILL CORNER US ROUTE 30 & ACUTT ROAD MONTGOMERY, IL 60538

[Map this facility](#)

[EPA Facility Information](#)

*This query was executed on AUG-12-2010*

---

#### Superfund Information (CERCLIS)

**CERCLIS EPA ID:** ILD980902134 **SITE SMSA:** 1600

**FEDERAL FACILITY:** N

**NPL STATUS:** Not on the NPL

Additional Information can be obtained from the Superfund [CERCLIS](#) Query.

Additional Superfund Site information may be obtained through EPA's [Superfund](#) web site. Their [query pages](#) provide an alternative method for retrieving Superfund Site information.

Additional information for CERCLIS sites may be obtained from National Library of Medicine (NLM) [EXIT EPA](#) [TOXMAP](#). This information resource is not maintained, managed, or owned by the Environmental Protection Agency (EPA) or the Envirofacts Support Team. Neither the EPA nor the Envirofacts Support Team is responsible for their content or site operation. The Envirofacts Warehouse provides this reference only as a convenience to our Internet users.

---



## Facility Registry System (FRS)

[http://oaspub.epa.gov/enviro/fii\\_query\\_dtl\\_disp\\_program\\_facility](http://oaspub.epa.gov/enviro/fii_query_dtl_disp_program_facility)  
Last updated on Thursday, August 12, 2010

You are here: [EPA Home](#) [Envirofacts](#) [FRS](#) Report



## Facility Detail Report



## PHILLIPS THOM LANDFILL

CORNER US ROUTE 30 & ACUTT ROAD  
MONTGOMERY, IL 60538  
EPA Registry Id: 110009326746

There is no valid (quality assured) locational data currently available in the FRS database for this facility.

## Environmental Interests

Information System	Information System ID	Environmental Interest Type	Data Source	Last Updated Date	Supplemental Environmental Interests:
COMPREHENSIVE ENVIRONMENTAL RESPONSE, COMPENSATION AND LIABILITY INFORMATION SYSTEM	ILD980902134	SUPERFUND	CERCLIS		

Additional EPA Reports: [MyEnvironment](#)

## Standard Industrial Classification Codes (SIC)

No SIC Codes returned.

## National Industry Classification System Codes (NAICS)

No NAICS Codes returned.

## Facility Codes and Flags

EPA Region:	05
Duns Number:	
Congressional District Number:	
Legislative District Number:	
HUC Code/Watershed:	
US Mexico Border Indicator:	NO
Federal Facility:	
Tribal Land:	NO

## Facility Mailing Addresses

No Facility Mailing Addresses returned.

## Contacts

No Contacts returned.

## Alternative Names

No Alternative Names returned.

## Organizations

No Organizations returned.

Query executed on: AUG-12-2010

## Additional information for CERCLIS or TRI sites:

*This information resource is not maintained, managed, or owned by the Environmental Protection Agency (EPA) or the Envirofacts Support Team. Neither the EPA nor the Envirofacts Support Team is responsible for their content or site operation. The Envirofacts Warehouse provides this reference only as a convenience to our Internet users.*

- National Library of Medicine (NLM) [EXIT EPA](#) [TOXMAP](#)




[http://oaspub.epa.gov/enviro/cerclis\\_web.report?pgm\\_sys\\_id=ILD980902134](http://oaspub.epa.gov/enviro/cerclis_web.report?pgm_sys_id=ILD980902134)

Last updated on Thursday, August 12, 2010

## Superfund (CERCLIS)

You are here: [EPA Home](#) [Envirofacts](#) [CERCLIS](#) [Query Results](#)

## Query Results

Report  
an  
Error

Site ID: Equal To: ILD980902134

Results are based on data extracted on JUL-22-2010

**Note:** Click on the underlined CORPORATE LINK value for links to that company's environmental web pages.

Click on the underlined MAPPING INFO value to obtain mapping information for the facility.

Click on the underlined RECORD OF DECISION value for a RODS Site Report.

Click on the underlined "View Facility Information" link to view EPA Facility information for the facility.

[Go To Bottom Of The Page](#)

<b>CERCLIS EPA ID:</b>	ILD980902134	<b>SITE NAME:</b>	PHILLIPS THOM LANDFILL
<b>STREET ADDRESS:</b>	CORNER US ROUTE 30 & ACUTT ROAD	<b>FACILITY INFORMATION</b>	<a href="#">View facility information</a>
<b>CITY NAME:</b>	MONTGOMERY		
<b>STATE ABBR:</b>	IL	<b>FEDERAL FACILITY:</b>	N
<b>ZIP CODE:</b>	60538	<b>NPL STATUS:</b>	Not on the NPL
<b>COUNTY NAME:</b>	KANE		
<b>CORPORATE LINK:</b>	No	<b>RECORD OF DECISION (ROD) INFO:</b>	No
<b>LATITUDE:</b>		<b>EPA REGIONAL LINK:</b>	No
<b>LONGITUDE:</b>		<b>MAPPING INFO:</b>	<a href="#">MAP</a>
<b>SITE SMSA:</b>	1600		

## Enforcement and Cleanup Actions

Action	Action ID	Actual Start Date	Actual End Date	Responsibility	Planned Outcome	Urgency
EXPANDED SITE INSPECTION	001	05/17/1996	11/18/1996	State, Fund Financed	Recommended for HRS Scoring	
SITE INSPECTION	001		06/25/1987	EPA Fund-Financed	Higher priority for further assessment	
PRELIMINARY ASSESSMENT	001		09/01/1984	State, Fund Financed	Low priority for further assessment	
DISCOVERY	001		02/01/1984	EPA Fund-Financed		


**Site Description**

There were no Site Descriptions reported for this site.

---

**Below is additional information for CERCLIS sites:**

*This information resource is not maintained, managed, or owned by the Environmental Protection Agency (EPA) or the Envirofacts Support Team. Neither the EPA nor the Envirofacts Support Team is responsible for their content or site operation. The Envirofacts Warehouse provides this reference only as a convenience to our Internet users.*

- National Library of Medicine (NLM)  [TOXMAP](#)
- 

[Go To Top Of The Page](#)

**Total Number of Facilities Displayed: 1**

---